# CTS-11088

Gold Piston Seals, 2/pk Comparable to: Agilent<sup>®</sup> 0905-1420



## **Technical Data Sheet**

### 1.0 Description

These seals are designed to be compatible with Agilent® 1050, 1100, 1120, 1200, 1220, 1260, G1310A/B, G1311A/B/C, G1312A/B/C, G1376A, G2226A and G4302A HPLC systems. They are comparable to Agilent® part number 0905-1420.

#### 2.0 Materials Specifications

UHMWPE w/Zinc Sterate

#### 3.0 Replacement Frequency

Beyond routine maintenance it may be necessary to replace the seals more frequently if they are operating in a high salt buffer concentration environment; or if the plungers are scratched or worn. Seals may also need replacing if the system fails its leak test.

#### 4.0 Installation Information

Sciencix parts are designed to be compatible and interchangeable with OEM parts. Please see instrument service manual for proper removal and installation procedure.

#### 5.0 Warranty

We view your business with us as a partnership based on mutual trust.

We extend a Lifetime Warranty against any manufacturing defects on all Sciencix HPLC repair parts. If a defect is identified, please contact us at 800.682.6480 or by email at <u>sales@sciencix.com</u> to report the issue. We will assist you with a resolution in a timely fashion.