

# CTS-0310

Ball & Seat Outlet Check Valve Rebuild Kit (rebuilds 2 valves)  
Comparable to: Waters® WAT026014



## Technical Data Sheet

---

### 1.0 Description


This kit is designed to be compatible with Waters 510, 515, 600, 610 and 1525EF HPLC systems. It is comparable to Waters part number WAT026014.

### 2.0 Materials Specifications

PTFE  
PCTFE  
Ruby  
Sapphire  
TFE

### 3.0 Installation Information

Sciencix parts are designed to be compatible and interchangeable with OEM parts. Please see instrument service manual for proper removal and installation procedure.



### 4.0 Warranty

We view your business with us as a partnership based on mutual trust.

We extend a Lifetime Warranty against any manufacturing defects on all Sciencix HPLC repair parts. If a defect is identified, please contact us at 800.682.6480 or by email at [sales@sciencix.com](mailto:sales@sciencix.com) to report the issue. We will assist you with a resolution in a timely fashion.